

Duncan Ellison

Tel. 01723 859573
Mobile 07582 893496
www.duncanellison.co.uk

MERCEDES BENZ 380SL

Registration B57 ADE

Mileage 54,640

Carry out full appraisal and complete full service and the following tasks:

Replace spark plugs.

Renew all 4 rubber drive belts

Test fuel injectors .Renew all 8 .

Replace electric aerial.

Replace o/s front shock absorber (oe spec bilstein)

Replace windscreen wiper blade rubbers and headlamp rubbers

Overhaul stuck headlamp wiper mechanism lubricate and synchronise.

Change engine oil and filter

Drain automatic gearbox and torque convertor. Remove sump pan and renew filter.

Refit pan and refill gearbox.

Remove n/s front exhaust manifold. Renew gaskets and EGR valve flange

Renew front brake discs and pads and at the same time remove all hub old grease and install fresh grease. Adjust hub end float.

Renew rear brake discs and pads

Replace bonnet under felt insulation

Check timing chain for any stretch whatsoever. Replace timing chain and cam cover rubber gaskets.

Remove front and rear bumpers and completely dismantle removing the chromes from the frame. Clean / wire wheel components as necessary and apply satin black 2k and clear Waxoyl (3 coats) as necessary to ensure the longevity of the bumpers.

Inspect bulkhead and inject Waxoyl inside cavities to ensure long life.

Inspect underside and all pipe work. Clean and top up Waxoyl as necessary.

Carry out protracted road testing.